

## **2.7 DN STEP IN ROOM TEMP IMAGES**

For documentation purposes, it should be noted that room temperature images taken during Solar Thermal Vacuum Testing exhibit a 40 DN step between lines 20 and 21, as well as a 40 DN step between lines 1 and 2 for the NAC. No cause has been established to date.